

Service Prices

GOSSEN			
MODEL	Service Cost:	Replacement Model:	Trade-In Price:
Color Pro 2/Color Pro 3	\$396.00	GO 4063	\$792.00
Digiflash	Trade In Only	GO 4007	\$151.92
Luna Lux	Trade In Only	GO 4033	\$194.40
Luna Pro Digital F	\$93.00	GO 4033	\$194.40
Luna Pro F	\$93.00	GO 4033	\$194.40
Luna Pro SBC	\$93.00	GO 4033	\$194.40
Luna Pro/S	Trade In Only	GO 4033	\$194.40
Luna Star F2	Discontinued	Call for Details	
Mavolux	Discontinued	Call for Details	
Mavo Monitor	Discontinued	Call for Details	
Multipro	\$93.00	GO 4033	\$194.40
Panlux	Discontinued	Call for Details	
Pilot 2	Trade In Only	GO 4006	\$108.00
Scout 3	Trade In Only	GO 4006	\$108.00
Starlite	Trade In Only	GO 4046	\$511.20
Ultra Pro	Trade In Only	GO 4046	\$511.20
Ultraspot/2	Trade In Only	GO 4046	\$511.20
GO 4006	\$54.00	GO 4006	\$108.00
GO 4007	\$75.96	GO 4007	\$151.92
GO 4033	\$97.20	GO 4033	\$194.40
GO 4046	\$255.60	GO 4046	\$511.20
GO 4056	\$313.20	GO 4056	\$626.40
GO 4056B	\$604.80	GO 4056B	\$1,209.60
GO 4063	\$396.00	GO 4063	\$792.00
GO 4068	\$716.40	GO 4068	\$1,432.80